## **Printers**

## **Removing Phantom Lines on Scans with Auto Document Feeder** (ADF)

If you are seeing lines on scans using your ADF, there's ink or debris on the scanning element.

Open up your scanner like you're going to use the flatbed and clean this part with some windex or alcohol (preferable).



## **Printers**

Unique solution ID: #1128 Author: n/a Last update: 2023-02-02 01:29