

Infrastructure

How to factory reset a Wx-Goos1 / IT Watchdogs Weather Goose 1

As you probably know as you're searching for this, there is no reset button on the Wx-Goos1. Here's how you can get into the admin/config if you forget the credentials.

Username: reset

Password: powerup<last 4 digits of serial>

Enter "powerup" + the last 4 digits of your serial #

Unique solution ID: #1168

Author: n/a

Last update: 2026-02-05 18:52