

# Management

## iDRAC Commands for Power On, Power Off, and Restart

In the event you have a Dell server where the iDRAC GUI is unresponsive, you can use the following telnet commands to perform power management functions:

```
/admin1/system1-> racadm serveraction hardreset  
/admin1/system1-> racadm serveraction powerdown  
/admin1/system1-> racadm serveraction powerup
```

When the operation is successful, you'll see the following response

```
Server power operation successful
```

Unique solution ID: #1047

Author: n/a

Last update: 2021-02-01 04:17